

Stucco Mix ratios

For a scratch coat, you will need this mixture:

1 part portland cement

1 part hydrated lime

2 1/2 to 4 parts [sand](#)

For a brown coat, you will need:

1 part portland cement

1 part hydrated lime

3 1/2 to 5 parts sand

[Finish coat](#) ingredients:

1 part portland cement

1 part hydrated lime

1 1/2 to 3 parts sand